







tecnica S.p.A.



© Limpieza Purotec

S.A.



Purotechn







© Limpieza Purotecnic S.A.





© Limpieza Purotecna S.







© Limpieza Purotec















© Limpieza Purotecnica S.A.



© Limpieza Purotecnica S.A.



© Limpieza Purotecnic S.A.



# Attaka 14 Subsea Tree & Wellhead Condition

## Attaka 14 Subsea Well

Water Depth : 182'

Wellhead : 18-3/4" SG-5, 10,000 psi Vetco Gray Wellhead

Subsea Tree : FMC-OSS-CM-1 Valve Type Tree

Tbg Hd - WH : Vetco Gray H4 Connector


Tree cap seems OK. No leak seen.  
Just covered by marine growth

Subsea tree-Tubing head connector  
seems OK. No leak seen. Just covered  
by marine growth

Tubing head seems OK. No leak seen.  
Top section of H connector seems OK  
as well, no leak

Subsea tree seems OK. No leak seen.  
Just covered by marine growth

Bottom part of H Connector cannot be  
seen clearly, but seems no leak





© Limpieza Pura



© Lupieza Purificadora S.A.





© Limpieza y Mantenimiento S.A.

Tree cap adapter  
after cleaning



© Intimpreza Purotecnică S.A.



© Limpieza Purotecnic S.A.



©

INNOVATION

TECHNOLOGICAL

Tree cap adapter  
covered by thick  
marine growth  
both hard & soft





Tree cap adapter covered by marine growth both hard and soft



© Li







© **Limpieza y Mantenencia S.A.**



Bubble gas

Grease fitting  
cap of manual  
annulus gate  
valve

© Limpieza Purotecnic S.A.



© Limpieza Purificadora S.A.



© Limpieza Purolite nica S.A.








© Limpieza Purotecnica S.A.



© Sieza S.A





Grease fitting  
cap of manual  
annulus gate  
valve



Grease fitting  
cap of manual  
annulus gate  
valve





© Limpieza Purotecnica S.A.



© Limpieza Purotecnica S.A.



© Limpia y Proteccion S.A.